
Definitions				
Abrasion Resistance	Ability to withstand smudging and scratching			
Darkness	Measure of the blackness of an image			
Print Window	Range of temperatures at which a ribbon prints			
Print Speed	Speed at which a ribbon prints and still produces acceptable images			
Scanability	Barcode scan acceptability			
Versatility	Range of materials a ribbon will print on			

Competitive Resin Comparison

High

Low

CONFIDENTIAL



Competitive Resin Comparison

CONFIDENTIAL

	Darwin	Heat Shield	Zebra 5095	AXR7+
Print Window	8	7	7	6
Print Speed	7	7	6	5
Versatility	9	7	7	4
Abrasion Resistance	9	8	7	7
Scanability	10	9	9	8
Darkness	9	8	9	7